

Hilton Motif Seattle 1415 5th Ave (Unit: 1) Seattle 98101 Date of Service Service Performed By 09/21/2022 Services Performed

Hood System Cleaning - 4 Trucks Filters, Back Wall, Shine

Thank you for your business! Please see our after-service pictures and notes below. Are you willing to help us by giving us a 5 star review? If so, click the *thumbs up* link below. If not, please click the *thumbs down* link so you can tell us how to improve our service and assist you better in the future.

BF,

Truck 18



If you need a printable after-service report, click here.

Deficiencies noted when service was performed




shows how we found hinge kit, I was able to fix it. it now is working just fine.



when fans are off grease drips down from duct. this no longer is an issue.



drips from duct onto the oven.



this shows how I found the access panel on the roof. gasket is torn and i was able to re-seat the panel



drips down from horizontal run of duct when fans are off.



grease from the fan tuned off dripping down, this was cleaned up.



this shows how I found the access panel #2 on the roof, I was able to re-seat gasket and panel correctly.

After photos







Apex: 09/21/2022, MOTIF Unit 1




















































Apex: 09/21/2022, MOTIF Unit 1











Apex: 09/21/2022, MOTIF Unit 1











Apex: 09/21/2022, MOTIF Unit 1
Image: Sector









